

Dependent Resurvey of the Boundaries, Seminole Indian Lands,
T. 48 S., R. 34 E., Tallahassee Meridian, Florida.

Chains

Land, almost level.
Soil, muck, 1st rate if drained.
Timber, none.

S. 1° 07' E., bet. secs. 31 and 36, marking the true line.

Over almost level land, through saw-grass. Along the boundary of Indian Land with unsurveyed land to the east.

19.88 Set a pine post, 4 ins. square, 5 ft. long, 30 ins. in the ground.

20.90 Enter a saw-grass pond, bears NW. and SE.

27.80 Leave pond, enter open grass land with scattering clumps of gallberry bushes, bears NE. and SW.

39.76 Proportionate distance; there is no remaining evidence of the original corner post or bearing tree.

Set an iron post, 3 ft. long, 1 in. diam., encased in concrete, 3 ft. long, 6 ins. diam., 26 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap mkd.,

$\frac{1}{4}$
 S 36 | S 31
 SIL |
 1939

No bearing trees available.

A pine post, 4 ins. square, 5 ft. long, 30 ins. in the ground, bears S. 45° W., 1 lk. dist.

59.64 Set a pine post, 4 ins. square, 5 ft. long, 24 ins. in the ground.

79.52 The point for the cor. of Tps. 48 and 49 S., Rs. 34 and 35 E., which was determined by using proportion between the cor. of Tps. 47 and 48 S., Rs. 34 and 35 E., and the cor. of Tps. 49 and 50 S., Rs. 34 and 35 E., for latitude position, and record distance from the cor. of Tps. 48 and 49 S., Rs. 33 and 34 E. for meridional position. This method of restoration was used as the land to the east has not been surveyed.

NOTE:

The south boundary of T. 48 S., R. 34 E., was resurveyed by the County Engineer of Collier County in 1938, by running easterly from the corner of Tps. 48 and 49 S., Rs. 33 and 34 E., without what is considered proper control for the corner of Tps. 48 and 49 S., Rs. 34 and 35 E. After developing control for the reestablishment of the corner of Tps. 48 and 49 S., Rs. 34 and 35 E., as described above, the County Engineer, Mr. J. H. T. McGee, was fully advised in the matter, and he agreed to the control as adopted. In order to avoid leaving two sets of monuments for the south boundary of the township, the monuments which had been set in the resurvey of 1938 were, by agreement with the County Engineer, moved to the proper positions and reset.

Set a Collier County concrete monument, 3 ft. long, 4 ins. square, 26 ins. in the ground, for the cor. of Tps. 48 and 49 S., Rs. 34 and 35 E. In the center of the monument is an iron pipe, 39 ins. long, 1 in. diam., protruding 3 ins. above the concrete. On the pipe is screwed a brass plate, 3 ins. diam., $\frac{1}{2}$ in. thick, mkd.,